



Attention

It has been brought to our attention that our website has been advertising that some of our globe and angle valves include an excess flow check. This is incorrect. Our globe and angle valves have never included an excess flow check feature and although this is obvious to the end user we feel it necessary to notify anyone that has purchased one with the expectation that it has an excess flow check feature. The part numbers include the A-2525-H and A-1625. See photos below.



If you have purchased these valves with the impression they have an excess flow check please make adjustments to your plumbing so that it meets your plumbing needs. If an in-line excess flow check is needed we have several solutions available.

Thank you,

Judd Stretcher
Continental NH3 Products.